RG104 E-1 Box 179 Mint of the United States at Philadelphia, Pa., Mewer 6 1893. Non O.B. Bostychell Deflenuteadest The Coining Bress Made by
the Perraeute Machine 6 Pridgeport & w not norking datisfactory - the Guid Dieces are brused on the edges (cents I sad all efforts on our part so far fail to remore the trouble The Signteen of food attacked to the press requires alteration to suit the Slauchet. Fronted reobsectfully Diggest that the Manufactures Sena Come one here to book offer this difficulty. Very Rosserfulle,
M. Dotteel

Mint of the United States at Philadelphia, Pa., Coiner's Office, January 6, 1893

Hon. O.C. Bosbyshell Superintendent

Sir:

The coining press made by the Ferracute Machine Co. Bridgeport N.J. is not working satisfactory – the coined pieces are bruised on the edges (cents) and all efforts on our part so far fail to remove the trouble. The system of feed attached to the press requires alteration to suit the planchets.

I would respectfully suggest that the manufacturer send some one here to look after this difficulty.

Very Respectfully W.S. Steel Coiner